



County of Riverside DEPARTMENT OF ENVIRONMENTAL HEALTH

For general information call: 1-888-722-4234

www.rivcoeh.org

INSPECTION REPORT

FACILITY NAME Broken Yolk Cafe					DATE 1/20/2022	TIME IN 3:15 PM	TIME OUT 4:00 PM
LOCATION 26495 Ynez Rd, Temecula, CA 92591						RE-INSPECTION DATE 5/20/2022	
PERMIT HOLDER Big Huevos Holdings LLC					E-MAIL randycorrigan1@gmail.com		
PERMIT # PR0083656	EXPIRATION DATE: 01/31/2023	SERVICE Facility closure	FACILITY PHONE #: (951)934-9655	PE 3622	DISTRICT 0046	INSPECTOR NAME Kristen Burnham	

Inspector Observations:

22. SEWAGE AND WASTEWATER PROPERLY DISPOSED

Violation Description: A facility must have an approved and properly functioning plumbing system at all times. All liquid waste must drain to an approved, fully functioning sewage disposal system. Fully functional restrooms must be provided for employee use during hours of operation. (114197, 114250)

Overall Inspection Comments

In response to complaint CO0081821 this facility was observed to have a failing grease interceptor. Fluid was observed to have emerged from the grease interceptor lids and flowed through the concrete ribbon gutter of the shopping center. Pooled greasy material is present on the surface of the ground near the interceptors.

The facility is hereby closed and may not reopen until approved to do so by this Department. Operating prior to receiving that approval will result in legal action. Do not dispose of any water within the facility that could result in further discharge from the grease interceptor: this includes ceasing all ware washing, food preparation, hand washing, and disposal of mop water. Functioning of the facility, including discharge of wastewater, must wait until reopening approval is granted.

In order to be reopened the grease interceptor must be restored to fully functional condition. The sewer lines must all be functional. Keep all service invoices regarding the clean up and/or repairs that the grease interceptor undergoes. The ground must also be properly cleaned of all run off caused by the interceptor. Ensure that all wastewater generated during cleaning is captured (vacuumed) as part of the clean up process. The approval to reopen must also be granted by all other pertinent agencies, such as City of Temecula Building & Safety.

If the repairs are completed by Friday 1-21-22, contact lead inspector Derrick Spencer at DSpencer@rivco.org or at 951-461-0284 to request the reopening evaluation appointment.

Signature

Signature not captured due to
COVID 19 pandemic.

Alieja Dzeljilji Kim
Person in Charge
01/20/2022

Kristen Burnham
Environmental Health Specialist
01/20/2022