

# County of Riverside DEPARTMENT OF ENVIRONMENTAL HEALTH

For general information call: 1-888-722-4234 www.rivcoeh.org

#### **INSPECTION REPORT**

FACILITY NAME						E	TIME IN	TIME OUT	
Le Poke-OOB						1/2021	1:45 PM	2:30 PM	
LOCATION							RE-INSPECTION DATE		
27315 Jefferson Ave Ste. K, Temecula, CA 92590							12/16/2021		
PERMIT HOLDER							E-MAIL		
Team Star Group Inc						lepokejefferson@gmail.com			
PERMIT#	EXPIRATION DATE:	SERVICE	FACILITY PHONE #:	PE	DISTRICT	INSPECTOR NAME			
PR0007034	01/31/2023	Facility closure	(951)719-3400	2620	0046	Kristen Burnham			

### **Inspector Observations:**

#### 21. HOT AND COLD WATER AVAILABLE

**Violation Description:** An adequate, protected, pressurized, potable supply of hot water and cold water shall be provided at all times. Hot water of at least 120°F must be provided for facilities with unpackaged food or packaged potentially hazardous food. Handwashing facilities shall be equipped to provide warm water for at least 15 seconds. (113953(c), 114189, 114192 (a,d), 114192.1, 114195)

## **Overall Inspection Comments**

During the response to complaint CO0078205, the facility was observed to be without hot water. The maximum temperature at the 3- compartment sink was 67 \*F. The facility was closed and a closure sign was posted.

Staff were directed to immediately cease any further food preparation or utensil washing activities.

Based on the number and types of plumbing fixtures in the facility, a water heater with a minimum 41,050 BTU rating must be installed. If a water heater with a lower rating than 41,050 BTU is installed, then it will require replacement with a new one. Please ensure the new water heater meets the minimum requirement.

Take a picture of the plate/label on the new water heater showing the BTU rating. The water heater location is above a mop sump and is not readily accessible by the inspector. This picture along with a copy of the receipt/invoice must be provided to the inspector.

The facility must remain closed until an inspector verifies that hot water is present and that the new water heater has the proper rating (strength). Email inspector when the installation is complete to schedule a reinspection.

Signature				
Signature not captured due to COVID 19 pandemic.	KBurha			
owners: David Kim and Jung Kim	Kristen Burnham			
Person in Charge	Environmental Health Specialist			
03/11/2021	03/11/2021			

10/31/2022 DAINSTUTJ Page 1 of 1